

**UTILITY RADIOLOGICAL SAFETY BOARD OF OHIO**  
**DAVIS-BESSE NUCLEAR POWER STATION ADMINISTRATION BUILDING**  
**5501 NORTH STATE ROUTE 2, OAK HARBOR, OHIO 43449**  
**OCTOBER 9, 2012 10:30 A.M.**  
**AGENDA**

**I. ROLL CALL**

**II. PLANT ANNOUNCEMENTS**

**III. APPROVAL OF THE JULY 9, 2012 MINUTES (TAB 2)**

**IV. OLD BUSINESS (TAB 3)**

- A. Updated Status of URSB Initiatives
- B. Midwestern Committee Report

**V. NEW BUSINESS (TAB 4)**

- A. New Ohio EMA Designee
- B. URSB WG Quarterly Reports
- C. Nuclear Regulatory Commission
  - 1. Oversight of First Energy Nuclear Operating Company Plants
  - 2. Cross Cutting Issue Process
- D. Utility Reports
  - 1. Beaver Valley Power Station
    - a. Outage
    - b. Evaluated Exercise
  - 2. Davis-Besse Nuclear Power Station
    - a. Shield Building Cracking – Results of Bore Hole Examination during Refueling Outage
    - b. Status of License Renewal
  - 3. Perry Nuclear Power Plant
    - a. Status of Cross-Cutting Areas of Human Performance
      - i. Reasons for Delaying NRC June 2012 Confirmatory Inspection
    - b. Fuel Leakage
  - 4. FENOC
    - a. Status of MIDAS program
    - b. Status of new Emergency Operations Facilities
    - c. Response to NRC's March 12, 2012 Letter Regarding Fukushima Recommendations

**VI. MISCELLANEOUS (TAB 5)**

- A. Dates of 2013 URSB Meetings
- B. Location of next URSB Meeting
- C. Questions from Public

**VII. ADJOURNMENT**